

TECHNICAL SPECIFICATION:

Display	UPPER :7Seg, 6digit, 0.56,RED LED display for KWH LOWER:7Seg, 4digit, 0.36,RED LED display for KW		
Size(mm)	96(H)X96(W)X50(D) mm		
Panel Cut out	92X92mm		
Voltage Input	30 To 300VAC P-N CATIII		
Current Input	0.1Amp To 5Amp AC direct or C.T Selectable up to 4000/5 ratio		
Active Power(KW)	0000-9999 KW		
Active Power (KWh)	0-999999 KWH		
Power Supply	230VAC, 50Hz, Approx. 4VA		
Frequency	45 To 65Hz		
Wiring System	3Ph-4W		
Protection Level	IP-65 (Front side) As per IS/IEC60529:2001		
Operating Temperature	0°C To 50°C	Relative Humidity	Up to 95% RH Non Condensing


CT PRIMARY SELECTION:

- 1) Press **SET** Key.
- 2) Now without releasing the key switch on the instrument.
- 3) Select required CT primary with **UP** and **DN** key.
- 4) To save Press **SET KEY**.

Display Selection:



Reset KWH&LDH

- 1) Press **UP/RST** KEY 10 sec.  KWH Reset message will display

- 2) Than release **Up/RST** Key & Press again to Reset KWh

